

WPR25LA083

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane's left wing damage as viewed from the rear. (Courtesy of Airplane Owner).



Photograph 2 - Airplane's left wing damage as viewed from the left side. (Courtesy of Airplane Owner).