

WPR25LA093

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident helicopter and hangar. (Courtesy of the FAA)



Photograph 3 - Hangar door and window. (Courtesy of the FAA)



Photograph 5 - Helicopter main rotor blade damage. (Courtesy of the FAA)