

WPR25LA095

INVESTIGATION PHOTOGRAPHS



Photograph 1
View of Airplane with Damaged Wing in Vineyard (Courtesy of Local Law Enforcement)



Photograph 2 - Substantially Damaged Fuselage (Courtesy of Local Law Enforcement)