

WPR25LA098

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of substantial damage to fuselage (Courtesy of airport manager)



Photograph 2 - View of substantial damage to fuselage (Courtesy of the FAA)



Photograph 3 - Accident site diagram (Courtesy of the student pilot)