

WPR25LA099

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane from forward (Courtesy of the FAA)



Photograph 2 - View of the airplane from the right (Courtesy of the FAA)



Photograph 3 - The fuel recovered from the right fuel tank (Courtesy of the FAA)