

WPR25LA104

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Bottom view right wing damage (Photo courtesy of pilot)



Photograph 2 - Top view of right-wing damage (Photo Courtesy of pilot)