

WPR25LA117

INVESTIGATION PHOTOGRAPHS

April 15, 2025



Photograph 1 - N171M, Fuselage damage. (Source airport manager)



Photograph 2 - Right wing damage. (Source airport manager)



Photograph 3 - Left wing damage. (Source airport manager)