

WPR25LA119

INVESTIGATION PHOTOGRAPHS



Photograph 1 - accident airplane (Courtesy of SQL Airport Operations)



Photograph 2 - substantially damaged left wing and aileron (Courtesy of SQL Airport Operations)



Photograph 3 - substantially damaged horizontal stabilizer (Courtesy of SQL Airport Operations)