

WPR25LA120

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane, right wing damage. (Courtesy of the pilot)



Photograph 2 - Accident airplane, right wing damage. (Courtesy of the pilot)



Photograph 4 - Accident airplane, right elevator damage. (Courtesy of the pilot)