

WPR25LA131

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of accident airplane (Courtesy of Pilot)



Photograph 2 - View of left wing damage (Courtesy of Pilot)



Photograph 3 - View of left wing damage (Courtesy of Pilot)