

WPR25LA157

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View impact area (Courtesy of Pilot)



Photograph 2 - View of runway braking (Courtesy of FAA)



Photograph 3 - View of firewall damage (Courtesy of FAA)