

WPR25LA162

INVESTIGATION PHOTOGRAPHS



Photograph 1 - The airplane at the accident site. (Courtesy of local law enforcement.)



Photograph 2 - View of substantial damage to the right wing. (Courtesy of local law enforcement.)



Photograph 3 - View of tire marks along the runway edge. (Courtesy of the FAA.)



Photograph 4 - View of grass along runway. (Courtesy of the FAA.)