

WPR25LA172

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aft view of accident airplane. (Courtesy of Spokane Valley Fire Dept.)



Photograph 2 - Forward view of accident airplane. (Courtesy of Spokane Valley Fire Dept.)



Photograph 3 - The accident site showing the destroyed structure along the runway edge and the accident airplane in the background. (Courtesy of Spokane Valley Fire Dept.)