

WPR25LA177

INVESTIGATION PHOTOGRAPH



Photograph 1 - View of substantial damage to the aft fuselage (Courtesy of FAA)