

WPR25LA179

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Damage to the Right Wing (Courtesy of the Pilot)



**Photograph 2 - Right Side View of Airplane Note Fuselage Damage Aft of the Landing Gear
(Courtesy of the Pilot)**



Photograph 3 - View of Damaged Right Side of Airplane (Courtesy of the Pilot)