

WPR25LA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View left wing damage (Courtesy of airport manager)



Photograph 2 - Front view of airplane (Courtesy of airport manager)