

WPR25LA191


## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of damage to the right wing (Courtesy of Pilot)**



**Photograph 2 - Top view of damage to right wing ribs (Courtesy of A&P)**



**Photo 3 - View of damage to outboard right aileron and attachment point (Courtesy of A&P)**



**Photo 4 - View of damage to right aileron leading edge and attachment points (Courtesy of A&P)**