

WPR25LA221


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage_Left Rear View (Courtesy of FAA)



Photograph 2 - Wreckage_Right Rear View (Courtesy of FAA)



Photograph 3 - Engine Controls (Courtesy of FAA)