

WPR25LA226

INVESTIGATION PHOTOGRAPHS



Photograph 1 - The airplane viewed from the left. (Courtesy of airport operations).



Photograph 2 - The airplane viewed from forward. (Courtesy of airport operations).



Photograph 3 - The pitot tube. (Courtesy of airport operations).