



Kristyn Blocher
Air Safety Investigator
AS-WPR

Date: 7/31/25

Subject: WPR25LA234

Contact: Todd Pryor, Spokane FSDO

The following is a synopsis of a telephone conversation with Mr. Pryor after his on site visit to the accident scene involving N759NB:

Mr. Pryor visited the accident site in Cashmere, WA on 7/31/25. He documented the airplane wreckage while impacted into the residence beyond the end of runway 07. He inspected the runway surface at 8S2 and documented rubber/tire signatures on the second half of runway 07, consistent with the landing gear tires of the accident airplane. He also documented a displaced runway end light, with rubber transfer marks on the post.