

WPR25LA239

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, view of lower side of wreckage. (Courtesy of the Gallatin County Sheriff's Office)



Photograph 2 - Accident site, view of the lower side of wreckage. (Courtesy of the Gallatin County Sheriff's Office)



**Photograph 3 - Accident site, view of the a main rotor blade, tailboom and aft fuselage.
(Courtesy of the Gallatin County Sheriff's Office)**



**Photograph 4 - Accident site, view of the tailboom.
(Courtesy of the Gallatin County Sheriff's Office)**



Photograph 6 - Accident site, view of the wreckage from the rear. (Courtesy of the Gallatin County Sheriff's Office)



Photograph 7 - Accident site, view of the wreckage from the front. (Courtesy of the Gallatin County Sheriff's Office)