

WPR25LA242

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane (Courtesy of Pilot)



Photograph 2 - Wrinkled Top Wing Skin (Courtesy of Pilot)



Photograph 3 - Distorted Fuselage Skin (Courtesy of Pilot)



Photograph 4 - Distorted Glare Shield and Support (Courtesy of Pilot)