

WPR25LA247

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Inverted Airplane showing fuselage and tail damage.
(Courtesy of Airport Manager)**



**Photograph 2 - Overturned airplane on grass runway post-accident.
((Courtesy of Airport Manager))**