

WPR25LA258

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of lower left wing damage (Courtesy of airport operations)**



**Photograph 2 - View of rudder damage (Courtesy of airport operations)**