

WPR25LA280 – Accident Location Photos



Figure 1: Airplane damage



Figure 2: Edge of runway and airplane location



Figure 3: Airplane tire marks, edge of runway, and final location



Figure 4: Airplane damage



Figure 5: Airplane landing gear damage (left side)



Figure 6: Airplane landing gear damage (from rear)



Figure 7: Left wing/aileron damage