

WPR25LA285

INVESTIGATION PHOTOGRAPHS



Photograph 1 - A view of substantial damage to the left wing. (Courtesy of the FAA.)



Photograph 2 - A view of substantial damage to the left wing. (Courtesy of the FAA.)



Photograph 3 - A view of the substantial damage to the left horizontal stabilizer. (Courtesy of the FAA.)