

WPR25LA287

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of wing strut damage (Courtesy of FAA)**



**Photograph 2 - View of damage to the bottom fuselage (Courtesy of FAA)**