


WPR25LA297

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft Final Position and Damage (via COE airport ops)



Photograph 2 - Aircraft Final Position and Damage (via COE airport ops)



Photograph 3 - Aircraft Final Position (via COE airport ops)



Photograph 4 - Aircraft Damage (via COE airport ops)



Photograph 5 - Overhead Diagram - Accident Location