

WPR25LA308

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Police Department)



Photograph 2 - View of left-wing damage (Courtesy of Police Department)



Photograph 3 - View of right-wing damage (Courtesy of Police Department)



Photograph 4 - View of displaced fuselage (Courtesy of Police Department)