


WPR26LA016


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Bottom of left wing damage (Courtesy of pilot)



Photograph 2 - Left wing Rib damage (Courtesy of maintenance)



Photograph 3 - Raised rivets indicating internal left wing damage (Courtesy of maintenance)