

WPR26LA018

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft Final Position and Damage (via pilot)



Photograph 2 - Aircraft Final Position and Damage (via pilot)



Photograph 3 - Aircraft Final Position (via pilot)



Photograph 4 - Aircraft Damage (via COE pilot)