


WPR26LA021

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damaged gondola (Courtesy of Pilot)



Photograph 2 - View of severed upright tube (Courtesy of Pilot)