

WPR26LA024

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right wing damage (Courtesy of pilot)



Photograph 2 - Close-up right-wing damage (Courtesy of pilot)