

WPR26LA025

INVESTIGATION PHOTOGRAPHS AND DIAGRAM



Photograph 1 - Airplane Empennage - Damage (Courtesy of FAA)



Photograph 2 - Rudder - Damage (Courtesy of FAA)



Photograph 3 - Vertical Stabilizer - Damage (Courtesy of FAA)



Photograph 4 - Vertical Stabilizer Damage On-Scene (Courtesy of FAA)



Photograph 5 - Rudder Damage On-Scene (Courtesy of FAA)