

WPR26LA029

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Side view of left-wing damage (Courtesy of Sheriff's Office)



Photograph 2 - Front view of left-wing damage (Courtesy of Sheriff's Office)