


WPR26LA044

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft Damage - Front View (Courtesy of Fresno Airport Operations)



Photograph 2 - Aircraft Damage - Right Wing (Courtesy of Fresno Airport Operations)