

WPR26LA046

INVESTIGATION PHOTOGRAPHS



Photograph 1 - The airplane at the accident site. (Courtesy of the FAA).



Photograph 2 - The airplane's fuselage, viewed from the right. (Courtesy of the FAA).



Photograph 3 - The airplane's wings and aft fuselage. (Courtesy of the FAA).