


WPR26LA066

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Lower left wing/aileron damage (Courtesy of KSEE Airport Ops)



Photograph 2 - Lower left aileron damage (Courtesy of KSEE Airport Ops)