

WPR26LA072

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site, main wreckage. (Courtesy of the Owner)



Photograph 2 - Accident site, main wreckage. (Courtesy of the Owner)



Photograph 3 - Accident site, fuselage damage. (Courtesy of the Owner)



Photograph 4 - Accident site, fuselage damage. (Courtesy of the Owner)



Photograph 5 - Accident site, right wing damage. (Courtesy of the Owner)