

WPR26LA077

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Side of Airplane (Courtesy of Pilot)



Photograph 2 - Right Side of Airplane (Courtesy of Pilot)



Photograph 3 - Wires struck by Airplane (Courtesy of Pilot)