

WPR26LA086

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter wreckage in a grass field as viewed from the front. (Courtesy of Operator).



Photograph 2 - Helicopter wreckage as viewed from the top front side with nylon cord wrapped around right skid. (Courtesy of Operator).