

WPR26LA087

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Pilot)



Photograph 2 - View of left-wing damage (Courtesy of Pilot)



Photograph 3 - View of left flaperon damage (Courtesy of Pilot)



Photograph 4 - View of bent fuselage tube (Courtesy of Pilot)