

WPR26LA088

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Cowl and Strut Damage (Curtesy of Pilot)



Photograph 2 - Bent Strut (Courtesy of Pilot)