

WPR26LA112

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right wing damage (Courtesy of the Federal Aviation Administration)



Photograph 2 - View of right wing damage (Courtesy of the Federal Aviation Administration)



Photograph 3 - View of left wing damage (Courtesy of Airport Operations)



Photograph 4 - View of left wing damage (Courtesy of Airport Operations)