

WPR26LA114

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Aircraft Damage (Courtesy of pilot)



Photograph 2 - Accident Aircraft Damage - Wing (Courtesy of pilot)



Photograph 3 - Accident Aircraft Damage - Empennage (Courtesy of pilot)



Photograph 4 - Accident Aircraft Damage Empennage (Courtesy of pilot)



Photograph 5 - Pre-Accident Flight Separated Tailwheel Assembly (Courtesy of pilot)



Photograph 5 - Pre-Accident Flight Separated Tailwheel Spring (Courtesy of pilot)