

WPR26LA118

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Hot air balloon basket, overview (Courtesy of pilot)



Photograph 2 - Fractured U-Tube (Courtesy of pilot)



Photograph 3 - Fractured wood basket structure (Courtesy of pilot)



Photograph 5 - Fractured wood skid structure (Courtesy of pilot)