

WPR26LA123

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airframe damage from front right (Courtesy of Sheriff's office)



Photograph 2 - View of airframe damage from rear left (Courtesy of Sheriff's office)



Photograph 3 - View of airframe damage from front left (Courtesy of Sheriff's office)



Photograph 4 - View of cockpit damage (Courtesy of Sheriff's office)