

WPR26LA148

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damaged right wing (Courtesy of pilot)



Photograph 2 - Damaged right wing (Courtesy of pilot)



Photograph 3 - Damaged left wing (Courtesy of pilot)



Photograph 4 - Damaged left wing (Courtesy of pilot)



Photograph 5 - Forward fuselage damage (Courtesy of pilot)