

WPR26LA172

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View from the left from of the helicopter showing the tail rotor and tree
(Courtesy of Pilot)**



Photograph 2 - View from the left rear of the helicopter showing the tree and damage to the vertical stabilizer (Courtesy of pilot)



Photograph 3 - View of damage to vertical stabilizer and tail rotor (Courtesy of Pilot)