

WPR26LA175

INVESTIGATION PHOTOGRAPHS



Photograph 1: Aircraft's wing as viewed from the top side. (Courtesy of Airport Manager).



Photograph 2 - Aircraft's right tire as viewed from the right side. (Courtesy of Airport Manager).



Photograph 3 - Aircraft's N-number. (Courtesy of Airport Manager).